



HVAC System Action Items
35 Ambewood HVAC

Inspected by: inspector1@jaxkneppers.com

Prepared by: Jax Kneppers

Company: JKA

Date of Inspection: 6/11/14

Prepared for: Owner





INSPECTION INFORMATION

Weather

Clear, Sunny, Windy



PRESENT AT INSPECTION

Present at this inspection.





Bedroom 1

ltem	Description	
HVAC	Damaged	A Maintenance Needed
	Add straps to ducts to restrain for seismic.	
	Flex duct in attic not restrained 06/11/2014 18:44 (PDT)	

Bathroom 2





ltem	Description	
HVAC	Damaged	3 Maintenance Needed
	Center the registered between marked light fixture locations.	
	Ceiling register needs to be centered 06/11/2014 18:41 (PDT)	

Master Bedroom

ltem	Description		
HVAC	Hvac	Damaged	3 Maintenance Needed
	Add 90 degree elbows at supply Ceiling registers above rear door missing 90* bend 06/11/2014 18:45 (PDT)	registers, make sure duct is fully extended.	

Study

ltem	Description		
HVAC	Hvac	Damaged	A Maintenance Needed





Study (continued)

HVAC (continued) The duct termination at the supply and return registers need 90 degree elbow, duct needs to be properly supported and all wrinkles removed. Supply and return registers in ceiling 06/11/2014 18:42 (PDT) Description The duct termination at the supply and return registers need 90 degree elbow, duct needs to be properly supported and all wrinkles removed. Improper flex duct installation 06/11/2014 18:42 (PDT)

Bedroom 3

ltem	Description	
HVAC	Damaged	3 Maintenance Needed
	Straighten out duct to remove wrinkles and install 90 degree transfer flow. Ceiling register without 90 elbow 06/11/2014 18:39 (PDT)	sition at register for smooth air

Laundry Room

ltem	Description	
HVAC	Damaged	A Maintenance Needed
	I	





Laundry Room (continued)

ltem	Description
HVAC (continued)	Provide proper support for duct. Duct supported on plumbing pipe not acceptable.
	Improperly supported flex duct 06/11/2014 18:40 (PDT)

Walk In Closet

ltem	Description		
HVAC	Register	Damaged	A Maintenance Needed
	Move register to left	side of framing cavity.	
	Register in wrong lo in ceiling 06/11/2014 18:46 (PD		